NEW UNDERGROUND STEEL FUEL STORAGE TANKS

TANKS TANKS

TANKS

TANKS

TANKS

TANKS

TANKS

TANKS TANKS

TANKS

TANKS

TANKS TANKS

TANKS

TANKS

TANKS

TANKS

Diameter	Length	Gauge (Thickness)	Weight (Pounds)	Price FOB Quarryville	
3'0"	5'6"	12	278	123.00	
4'0''				220.00	
4'0"	6'0"	7		274.00	
4'0"	10'8"	10		324.00	
4'0"	10'8"			406.00	
5'4"	6'0''	7		378.00	
5'4"	9'0''	7	•	509.00	
5'4"	12'0"	7		620.00	
5'4"	17'11"	7		837.00	
5'4"	23'10"	7		1055.00	
8'0"	13'7''	1/4"		1821.00	
8'0''	16'0"			1926.00	
8'0''	21'4"	1/4"		2414.00	
8'0''	26'8''			2847.00	
10'0''	17'0''			2610.00	
8'0''	32'0"			3310.00	
10'0"	20'6"			2969.00	
10'6"	18'7''	1/4"		2978.00	
8'0''	40'0"	5/16"	•	5003.00	
10'6"	23'2"	5/16"	•	4575.00	
10'6"	31'0"	5/16"		5716.00	
10'6"	38'9''	3/8''		7600.00	
10'6''	46'6"	3/8''	27,923	8800.00	
	3'0" 4'0" 4'0" 4'0" 5'4" 5'4" 5'4" 5'4" 8'0" 8'0" 8'0" 10'0" 10'6" 10'6" 10'6" 10'6"	3'0" 5'6" 4'0" 6'0" 4'0" 10'8" 4'0" 10'8" 5'4" 6'0" 5'4" 9'0" 5'4" 12'0" 5'4" 17'11" 5'4" 23'10" 8'0" 16'0" 8'0" 21'4" 8'0" 26'8" 10'0" 17'0" 8'0" 32'0" 10'6" 18'7" 8'0" 40'0" 10'6" 33'9"	3'0" 5'6" 12 4'0" 6'0" 10 4'0" 6'0" 7 4'0" 10'8" 10 4'0" 10'8" 7 5'4" 6'0" 7 5'4" 9'0" 7 5'4" 12'0" 7 5'4" 12'0" 7 5'4" 13'7" 1/4" 8'0" 16'0" 1/4" 8'0" 21'4" 1/4" 8'0" 26'8" 1/4" 10'0" 17'0" 1/4" 8'0" 32'0" 1/4" 10'0" 20'6" 1/4" 10'6" 18'7" 1/4" 8'0" 40'0" 5/16" 10'6" 31'0" 5/16" 10'6" 38'9" 3/8"	3'0" 5'6" 12 278 4'0" 6'0" 10 549 4'0" 6'0" 7 751 4'0" 10'8" 10 827 4'0" 10'8" 7 1,129 5'4" 6'0" 7 1,028 5'4" 9'0" 7 1,388 5'4" 12'0" 7 1,735 5'4" 12'0" 7 1,735 5'4" 17'11" 7 2,432 5'4" 23'10" 7 3,130 8'0" 13'7" 1/4" 4,484 8'0" 16'0" 1/4" 5,588 8'0" 21'4" 1/4" 6,981 8'0" 26'8" 1/4" 8,375 10'0" 17'0" 1/4" 7,829 8'0" 32'0" 1/4" 9,768 10'0" 20'6" 1/4" 9,768 10'0" 20'6" 1/4" 8,946 10'6" 18'7" 1/4" 7,900 8'0" 40'0" 5/16" 14,823 10'6" 23'2" 5/16" 11,857 10'6" 31'0" 5/16" 15,105 10'6" 38'9" 3/8" 23,883	

Tanks are fabricated in strict accordance with the specifications of Underwriters' Labratories, Inc Exteriors of underground tanks are coated with black asphaltum paint Exteriors of above ground tanks are coated with red primer STI P3 system of corrosion protection for underground steel storage tanks available at an additional charge. We can provide timely delivery anywhere from 2 locations: Quarryville, PA; and Clarksville, Virginia. Contact us for delivery costs. We invite inquiries by phone or mail.

USED STEEL FUEL STORAGE TANKS

Capacity (Gallons)	Diameter	Length	Gauge (Thickness)	Weight (Pounds)	Price FOB Quarryville
275* 3,000 4,000 6,000 8,000 10,000	27'' 5'4'' 5'4'' 8'0'' 8'0''	5' 17'11'' 23'10'' 16'2'' 21'6'' 26'8''	14 7 7 1/4" 1/4" 1/4"	250 2,432 3,130 5,123 6,475 8,375	160 150 to 300 250 to 500 500 to 660 700 to 880 1100

Used tanks and used tank shells may not bear underwriters' label nor are coated with black asphaltum paint

NEW GASBOY FUEL PUMPS


Model	Description	G.P.M.	Price F.O.B. Quarryville
1230C	Complete w/counter, rotary hand type	20	126.00
60	12V DC w/meter	12	'372.00
72	115V w/meter	14-15	'375.00
1820	115V w/meter, w/cabinet	14-15	'413.00
1820K	115V, same as Model 1820 w/2 units, Keytrol	14-15	'513.00
390	115V w/Meter	14-15	'516.00

NEW FILL-RITE FUEL PUMPS

Model	Description	G.P.M.	Price F.O.B. Quarryville
NP 701	115V w/Meter	14-15	'354.00

LOW PRICE PROTECTION POLICY:

Within 30 days of purchase if someone advertises or offers at a lower price the same tank you have already purchased from us, let us know, because we'll pay you the difference!



An Additional 1% DISCOUNT is offered if paid by Cash Money or Certified Check

HOWARD E. GROFF CO.

Over Forty Years of Reliable Service Fuel Oil, Gasoline, and Coal 111 E. State Street, Quarryville, PA 17566

Phone: 717-786-2166

Mon.-Fri.: 8 AM - 4 PM Sat. 8 AM - 12 Noon

Sire Power creates post

TUNKHANNOCK — Bob Baker, of Carlisle, is named to a newly created position of District Programs Coordinator for Sire Power, Inc. He will coordinate programs and policies mainly in Southcentral and Western Pa., and also assist with programs on the national level, according to Michael Creek, Sire Power's National Sales Manager.

Baker will continue to develop and establish representation for Sire Power throughout the Southcentral and Western Pa. region, and assist with other regions as necessary. His duties and responsibilities will include assisting District Sales Managers in A.I. Training Schools, and herd visits promoting Sire Power programs, such as the GOLD Sire Development Program and LAMP (Linear Appraisal and Mating Program). He will also organize informational and promotional meetings, recruit and train technicians, and assist with exhibits and trade shows. Bob will coordinate the directives and programs to expand the representation of Sire Power.

He formerly served as a Sire Power Direct Herd Representative for Southcentral, Pa. for eight years. He developed and increased one of the best sales areas in the organization while in this position.

He began his A.I. career in 1946



Bob Baker

as a technician with the Cumberland County Artificial Breeders Co-op of which he later became the local unit manager. He received his A.I. training at Penn State University. In the 27 years as a technician with different A.I. Co-ops and organizations, Bob bred 95,000 first services. He received the 35,000 cow award from NAAB and the Quarter Century Award. Bob was raised on an Ayrshire farm in Cumberland County.

He and his wife, Mary, will continue to reside in Carlisle.

Mastitis report available

KALAMAZOO, Mich. — A management report on the importance and use of a complete mastitis management program is now available from TUCO, Division of The Upjohn Company.

The four-page report describes why mastitis is the most costly disease facing the dairy industry today and includes advice from experts on how good dairy management practices can successfully combat the disease.

It also includes reports from dairy producers who have had

success in controlling mastitis, explaining how good management treatment practices have led to their success. Their use of Albacillin for treating lactating cows, and the infusion of Albadry Plus or Biodry for dry cow treatment are also explained.

For a single copy of the report, or for more information, write: Mastitis Treatment Report, TUCO, Division of The Upjohn Company, P.O. Box 5087, Kalamazoo, MI 49003.

Butler Mall

(Continued from Page D10)

adhering to Association regulations, is eligible to receive points toward the Association's year-end banquet.

Membership is open to pullers

and non-pullers alike who reside in western Pennsylvania.

Kummer summed up the Mall show by saying that, "We're out to have some fun and to put on a good show!"

ATTENTION DAIRYMEN

STOP LOSING COWS A LITTLE MONEY NOW FOR GROOVING CAN SAVE LOTS OF MONEY LATER

The TMI "EDGE" provides clean, straight grooves in feed alleys, freestalls, holding lots and corners for improved traction, heat detection and drainage and the reduction of broken bones and splitting.

Group rates available!

CALL OR WRITE:

TRACTION MASTERS, INC.

Merle Becker 224 S. Market St. Ephrata, PA 17522 (717) 738-1359 Darl M. Packard 1514 Hollins St. Baltimore, MD 21223 (301) 945-7313