Dryer Vent Safety

CHICAGO, II. — Your shiny new dryer probably offers a wider selection of special fabric cycles, a larger door opening for fast loading and unloading and an easy-to-reach lint screen—all conveniences missing on that 20-year-old model that just died. Best of all, this larger capacity model fits right into the space vacated by the old dryer.

But before connecting your new dryer to the old exhaust vent, home economists from Whirlpool Corporation urge you to make a safety check of its existing ductwork. "That exhaust venf system is probably as ancient as the original dryer and may be clogged with lint or made of a material that's combustible" they explain

combustible," they explain.

Whirlpool home economists note that many older dryers were vented with flexible vinyl ducting, a type of ducting no longer recommended by testing organizations such as Underwriters Laboratories (UL) or by dryer manufacturers.

Tests indicate that flexible vinyl ducting tends to collect and

hold lint in its creases, creating a potentfal fire hazard. Vinyl also melts at high temperatures, preventing it from containing a fire as well as metal ductwork can.

So, when installing a new dryer, Whirlpool home economists encourage homeowners to make the following safety checks to ensure that the dryer is connected to proper metal ductwork that has unblocked air flow:

• If ductwork is made of vinyl or other combustible material, replace it with 4-inch diameter rigid or flexible metal ducting.

• For a vent system with metal

ductwork, check to make sure it meets the manufacturer's recommendations for correct installation. Is it the correct length and generally straight with as few elbows as possible?


 Vacuum ductwork sections to make sure they're clean and free of lint.

Check the outside end of the ducting to see that it's uncovered. A covering (such as a grill screen, bag, stocking, etc.), can trap lint inside the ductwork, blocking dryer air flow. This can result in longer drying times, higher ener-

gy use and conditions that can cause a fire.

• Check the outside vent outlet to be sure it exhausts into an open area. Is it visible, easy to reach for cleaning and at least one foot above the ground to allow good air circulation? Never end dryer venting under a house or porch or in an air shaft, crawl space, attic, chimney or other hidden area.

• Follow your dryer manufacturer's instructions for cleaning the venting system. Depending on use, the ductwork should be cleaned every one to two years.



SEE THE RED WING DEALER NEAREST YOU - WHERE SERVICE IS A WAY OF LIFE

Fitting You Right Is Our #1 Priority.

ALLENSVILLE
Allensville Shoe Shop
Box 7 Star Route

ALLENTOWN Red Wing Shoe Store 1031 Union Blvd. 215-432-6455

CHAMBERSBURG Shoemaker's Sporting Goods 763 S. Second St. 717-263-4124

HONEY PROOK
Brandywine Shoe Shop

HUGHESVILLE Marks Shoe & Repair 22 South Main 717-584-2616

KUTZTOWN Waynes Dry Goods 271-273 W. Main St. 215-683-7686

MADISONBURG
Fisher Harness & Shoe Shop
Star Route, Box 47

MARTINSBURG Zimmerman Harness RD 2 Box 36 814-793-3961 MIFFLINTOWN
Lost Creek Shoe Shop
RD #1 Box 88

OUARRYVILLE Books Shoe Service 107 E. State St. 717-786-2795

REHRERSBURG Leo's Shoe Store Godfrey St. 717-933-8169 SPRINGFIELD
Red Wing Shoe Store237 Baltimore Pike
215-544-1664

WILLIAMSPORT
Leesers Shoes
2000 E 3rd St.
On Williamsports Golden Strip
717-326-0211

