




## Mummau Tire Service Centers


# Call Us First

### For In-Field Farm Tire Service



**One call is all it takes for:**

- ✓ Fast response from highly trained professionals
- ✓ Fully equipped service trucks
- ✓ Farm tire replacement deliveries
- ✓ On-the-spot tire repairs and calcium service



## Your Firestone Farm, Forestry & Flotation Tire Headquarters

<p><b>GOOD</b></p> <p><b>Traction Field &amp; Road</b></p>  <table border="0"> <tr><td>13 6-38</td><td>6 ply</td><td><b>267.95</b></td></tr> <tr><td>15 5-38</td><td>6 ply</td><td><b>254.95</b></td></tr> <tr><td>16 9-30</td><td>6 ply</td><td><b>289.95</b></td></tr> <tr><td>18 4-34</td><td>6 ply</td><td><b>329.95</b></td></tr> </table>	13 6-38	6 ply	<b>267.95</b>	15 5-38	6 ply	<b>254.95</b>	16 9-30	6 ply	<b>289.95</b>	18 4-34	6 ply	<b>329.95</b>	<p><b>BETTER</b></p> <p><b>Super All Traction 23°</b></p> <p><b>NEW!</b></p>  <table border="0"> <tr><td>18 4-34</td><td>8 ply</td><td><b>419.95</b></td></tr> <tr><td>18 4-38</td><td>6 ply</td><td><b>424.95</b></td></tr> <tr><td>20 8-38</td><td>8 ply</td><td><b>594.95</b></td></tr> </table>	18 4-34	8 ply	<b>419.95</b>	18 4-38	6 ply	<b>424.95</b>	20 8-38	8 ply	<b>594.95</b>	<p><b>RADIAL 23°</b></p> <p>16.9R-38* <b>479.95</b></p> <p>18.4R-34* <b>511.95</b></p> <p>18.4R38* <b>519.95</b></p> <p>20.8R38* <b>679.95</b></p>	<p><b>BEST</b></p> <p><b>Radial All Traction FWD</b></p>  <table border="0"> <tr><td>14 9R28***</td><td><b>479.95</b></td></tr> <tr><td>16 9R26**</td><td><b>594.95</b></td></tr> <tr><td>16.9R28**</td><td><b>539.95</b></td></tr> </table>	14 9R28***	<b>479.95</b>	16 9R26**	<b>594.95</b>	16.9R28**	<b>539.95</b>	<p><b>BEST</b></p> <p><b>Radial All Traction 23°</b></p>  <table border="0"> <tr><td>18 4R38*</td><td><b>559.95</b></td></tr> <tr><td>20 8R38*</td><td><b>739.95</b></td></tr> <tr><td>18.4R42**</td><td><b>719.95</b></td></tr> </table>	18 4R38*	<b>559.95</b>	20 8R38*	<b>739.95</b>	18.4R42**	<b>719.95</b>																					
13 6-38	6 ply	<b>267.95</b>																																																								
15 5-38	6 ply	<b>254.95</b>																																																								
16 9-30	6 ply	<b>289.95</b>																																																								
18 4-34	6 ply	<b>329.95</b>																																																								
18 4-34	8 ply	<b>419.95</b>																																																								
18 4-38	6 ply	<b>424.95</b>																																																								
20 8-38	8 ply	<b>594.95</b>																																																								
14 9R28***	<b>479.95</b>																																																									
16 9R26**	<b>594.95</b>																																																									
16.9R28**	<b>539.95</b>																																																									
18 4R38*	<b>559.95</b>																																																									
20 8R38*	<b>739.95</b>																																																									
18.4R42**	<b>719.95</b>																																																									
<p><b>Flotation 23° DT</b></p>  <p>66x43 00-25 10 Ply <b>2095.95</b></p>	<p><b>All Traction Utility (Rear Backhoe)</b></p>  <table border="0"> <tr><td>17 5L24</td><td>8 ply</td><td><b>279.95</b></td></tr> <tr><td>19 5L24</td><td>10 ply</td><td><b>439.95</b></td></tr> </table>	17 5L24	8 ply	<b>279.95</b>	19 5L24	10 ply	<b>439.95</b>	<p><b>Forestry Special</b></p>  <table border="0"> <tr><td>18.4-26 - 10 ply</td><td><b>759.95</b></td></tr> <tr><td>23.1-26 - 10 Ply</td><td><b>1199.95</b></td></tr> </table>	18.4-26 - 10 ply	<b>759.95</b>	23.1-26 - 10 Ply	<b>1199.95</b>	<p><b>All Non Skid</b></p>  <table border="0"> <tr><td>18 4-16.1</td><td>6 ply</td><td><b>314.95</b></td></tr> <tr><td>14 9-24</td><td>.6 ply</td><td><b>304.95</b></td></tr> </table>	18 4-16.1	6 ply	<b>314.95</b>	14 9-24	.6 ply	<b>304.95</b>																																							
17 5L24	8 ply	<b>279.95</b>																																																								
19 5L24	10 ply	<b>439.95</b>																																																								
18.4-26 - 10 ply	<b>759.95</b>																																																									
23.1-26 - 10 Ply	<b>1199.95</b>																																																									
18 4-16.1	6 ply	<b>314.95</b>																																																								
14 9-24	.6 ply	<b>304.95</b>																																																								
<p><b>Champion Guide 3 Rib Front</b></p>  <table border="0"> <tr><td>6 00-16</td><td>4 ply</td><td><b>39.95</b></td></tr> <tr><td>7 50-16</td><td>6 ply</td><td><b>55.95</b></td></tr> <tr><td>11L15</td><td>8 ply</td><td><b>89.95</b></td></tr> <tr><td>10 00-16</td><td>8 ply</td><td><b>91.95</b></td></tr> </table>	6 00-16	4 ply	<b>39.95</b>	7 50-16	6 ply	<b>55.95</b>	11L15	8 ply	<b>89.95</b>	10 00-16	8 ply	<b>91.95</b>	<p><b>Champion Guide 4 Rib Front</b></p>  <table border="0"> <tr><td>9 5L15</td><td>6 ply</td><td><b>68.95</b></td></tr> <tr><td>7 50-16</td><td>8 ply</td><td><b>67.95</b></td></tr> <tr><td>11 00-16</td><td>8 ply</td><td><b>104.95</b></td></tr> <tr><td>14L16 1</td><td>8 ply</td><td><b>223.95</b></td></tr> </table>	9 5L15	6 ply	<b>68.95</b>	7 50-16	8 ply	<b>67.95</b>	11 00-16	8 ply	<b>104.95</b>	14L16 1	8 ply	<b>223.95</b>	<p><b>Rib Implement</b></p>  <table border="0"> <tr><td>5 00-15</td><td>4 ply</td><td><b>36.95</b></td></tr> <tr><td>7 60-15V</td><td>8 ply</td><td><b>46.95</b></td></tr> <tr><td>10.00-15</td><td>8 ply</td><td><b>76.95</b></td></tr> <tr><td>12.5L15</td><td>8 ply</td><td><b>68.95</b></td></tr> </table>	5 00-15	4 ply	<b>36.95</b>	7 60-15V	8 ply	<b>46.95</b>	10.00-15	8 ply	<b>76.95</b>	12.5L15	8 ply	<b>68.95</b>	<p><b>Firestone AT Field and Road</b></p>  <table border="0"> <tr><td>6-12</td><td>4 ply</td><td><b>54.95</b></td></tr> <tr><td>7-16</td><td>6 ply</td><td><b>94.95</b></td></tr> <tr><td>816</td><td>4 ply</td><td><b>102.95</b></td></tr> </table>	6-12	4 ply	<b>54.95</b>	7-16	6 ply	<b>94.95</b>	816	4 ply	<b>102.95</b>	<p><b>Firestone Turf &amp; Field</b></p>  <table border="0"> <tr><td>25x8 50-14</td><td>4 ply</td><td><b>76.95</b></td></tr> <tr><td>27x8.50-15</td><td>4 ply</td><td><b>82.95</b></td></tr> <tr><td>13 6-16</td><td>4 ply</td><td><b>209.95</b></td></tr> </table>	25x8 50-14	4 ply	<b>76.95</b>	27x8.50-15	4 ply	<b>82.95</b>	13 6-16	4 ply	<b>209.95</b>
6 00-16	4 ply	<b>39.95</b>																																																								
7 50-16	6 ply	<b>55.95</b>																																																								
11L15	8 ply	<b>89.95</b>																																																								
10 00-16	8 ply	<b>91.95</b>																																																								
9 5L15	6 ply	<b>68.95</b>																																																								
7 50-16	8 ply	<b>67.95</b>																																																								
11 00-16	8 ply	<b>104.95</b>																																																								
14L16 1	8 ply	<b>223.95</b>																																																								
5 00-15	4 ply	<b>36.95</b>																																																								
7 60-15V	8 ply	<b>46.95</b>																																																								
10.00-15	8 ply	<b>76.95</b>																																																								
12.5L15	8 ply	<b>68.95</b>																																																								
6-12	4 ply	<b>54.95</b>																																																								
7-16	6 ply	<b>94.95</b>																																																								
816	4 ply	<b>102.95</b>																																																								
25x8 50-14	4 ply	<b>76.95</b>																																																								
27x8.50-15	4 ply	<b>82.95</b>																																																								
13 6-16	4 ply	<b>209.95</b>																																																								

Central Warehouse  
1916 W. Main Street, Mt. Joy, Pa. 17552  
717-653-1260

Branch Warehouse  
Northumberland, Pa.  
717-473-3974 1-800-257-5908

### MUMMAU TIRE SERVICE CENTER

In Pa., Call Toll Free: 1-800-222-1729 NJ, DEL. & MD. - Call 1-800-688-3054

**Firestone**

THE LEADER IN THE FIELD