




# Mummau Tire Service Centers


# Call Us First

## For In-Field Farm Tire Service



### One call is all it takes for:

- ✓ Fast response from highly trained professionals
- ✓ Fully equipped service trucks
- ✓ Farm tire replacement deliveries
- ✓ On-the-spot tire repairs and calcium service



## Your Firestone Farm, Forestry & Flotation Tire Headquarters

<p><b>GOOD</b></p>  <p><b>Traction Field &amp; Road</b></p> <table border="0"> <tr><td>8 3-24</td><td>4 ply</td><td><b>104.95</b></td></tr> <tr><td>11 2-24</td><td>4 ply</td><td><b>134.95</b></td></tr> <tr><td>13 6-28</td><td>4 ply</td><td><b>164.95</b></td></tr> <tr><td>16 9-34</td><td>6 ply</td><td><b>314.95</b></td></tr> </table>	8 3-24	4 ply	<b>104.95</b>	11 2-24	4 ply	<b>134.95</b>	13 6-28	4 ply	<b>164.95</b>	16 9-34	6 ply	<b>314.95</b>	<p><b>BETTER</b></p>  <p><b>Super All Traction 23°</b></p> <table border="0"> <tr><td>18 4-34</td><td>6 ply</td><td><b>374.95</b></td></tr> <tr><td>18 4-38</td><td>6 ply</td><td><b>424.95</b></td></tr> <tr><td>20 8-38</td><td>8 ply</td><td><b>614.95</b></td></tr> </table>	18 4-34	6 ply	<b>374.95</b>	18 4-38	6 ply	<b>424.95</b>	20 8-38	8 ply	<b>614.95</b>	<p><b>SKIDSTEER</b></p> <p><b>10-16.5 6 Ply</b></p> <p><b>\$74.95</b></p>	<p><b>GOOD</b></p>  <p><b>Radial 23°</b></p> <table border="0"> <tr><td>18 4R34*</td><td><b>529.95</b></td></tr> <tr><td>15 5R38*</td><td><b>359.95</b></td></tr> <tr><td>16 9R38*</td><td><b>499.95</b></td></tr> </table>	18 4R34*	<b>529.95</b>	15 5R38*	<b>359.95</b>	16 9R38*	<b>499.95</b>	<p><b>BETTER</b></p>  <p><b>Radial All Traction 23°</b></p> <table border="0"> <tr><td>18 4R38*</td><td><b>579.95</b></td></tr> <tr><td>20.8R38*</td><td><b>759.95</b></td></tr> <tr><td>18 4R42**</td><td><b>737.95</b></td></tr> </table>	18 4R38*	<b>579.95</b>	20.8R38*	<b>759.95</b>	18 4R42**	<b>737.95</b>																					
8 3-24	4 ply	<b>104.95</b>																																																								
11 2-24	4 ply	<b>134.95</b>																																																								
13 6-28	4 ply	<b>164.95</b>																																																								
16 9-34	6 ply	<b>314.95</b>																																																								
18 4-34	6 ply	<b>374.95</b>																																																								
18 4-38	6 ply	<b>424.95</b>																																																								
20 8-38	8 ply	<b>614.95</b>																																																								
18 4R34*	<b>529.95</b>																																																									
15 5R38*	<b>359.95</b>																																																									
16 9R38*	<b>499.95</b>																																																									
18 4R38*	<b>579.95</b>																																																									
20.8R38*	<b>759.95</b>																																																									
18 4R42**	<b>737.95</b>																																																									
<p><b>Flotation 23° DT</b></p>  <p>48x31 00-20 12 Ply</p> <p><b>1569.95</b></p>	<p><b>All Traction Utility (Rear Backhoe)</b></p>  <table border="0"> <tr><td>17 5L24</td><td>8 ply</td><td><b>279.95</b></td></tr> <tr><td>19 5L24</td><td>10 ply</td><td><b>439.95</b></td></tr> </table>	17 5L24	8 ply	<b>279.95</b>	19 5L24	10 ply	<b>439.95</b>	<p><b>12-16.5 8 Ply</b></p> <p><b>\$104.95</b></p>	<p><b>Forestry Special</b></p>  <table border="0"> <tr><td>18 4-26 - 10 ply</td><td><b>759.95</b></td></tr> <tr><td>23 1-26 - 10 Ply</td><td><b>1199.95</b></td></tr> </table>	18 4-26 - 10 ply	<b>759.95</b>	23 1-26 - 10 Ply	<b>1199.95</b>	<p><b>All Non Skid</b></p>  <table border="0"> <tr><td>18 4-16 1 . 6 ply</td><td><b>289.95</b></td></tr> <tr><td>14 9-24 . 6 ply</td><td><b>262.95</b></td></tr> </table>	18 4-16 1 . 6 ply	<b>289.95</b>	14 9-24 . 6 ply	<b>262.95</b>																																								
17 5L24	8 ply	<b>279.95</b>																																																								
19 5L24	10 ply	<b>439.95</b>																																																								
18 4-26 - 10 ply	<b>759.95</b>																																																									
23 1-26 - 10 Ply	<b>1199.95</b>																																																									
18 4-16 1 . 6 ply	<b>289.95</b>																																																									
14 9-24 . 6 ply	<b>262.95</b>																																																									
<p><b>Champion Guide 3 Rib Front</b></p>  <table border="0"> <tr><td>6 00-16</td><td>4 ply</td><td><b>39.95</b></td></tr> <tr><td>7 50-16</td><td>6 ply</td><td><b>58.95</b></td></tr> <tr><td>11L15</td><td>8 ply</td><td><b>89.95</b></td></tr> <tr><td>10 00-16</td><td>8 ply</td><td><b>91.95</b></td></tr> </table>	6 00-16	4 ply	<b>39.95</b>	7 50-16	6 ply	<b>58.95</b>	11L15	8 ply	<b>89.95</b>	10 00-16	8 ply	<b>91.95</b>	<p><b>Champion Guide 4 Rib Front</b></p>  <table border="0"> <tr><td>9 5L15</td><td>6 ply</td><td><b>79.95</b></td></tr> <tr><td>7 50-16</td><td>8 ply</td><td><b>69.95</b></td></tr> <tr><td>11 00-16</td><td>8 ply</td><td><b>109.95</b></td></tr> <tr><td>14L16 1</td><td>8 ply</td><td><b>223.95</b></td></tr> </table>	9 5L15	6 ply	<b>79.95</b>	7 50-16	8 ply	<b>69.95</b>	11 00-16	8 ply	<b>109.95</b>	14L16 1	8 ply	<b>223.95</b>	<p><b>Rib Implement</b></p>  <table border="0"> <tr><td>5 00-15</td><td>4 ply</td><td><b>38.95</b></td></tr> <tr><td>7.60-15\</td><td>8 ply</td><td><b>49.95</b></td></tr> <tr><td>10 00-15</td><td>8 ply</td><td><b>78.95</b></td></tr> <tr><td>12 5L15</td><td>8 ply</td><td><b>70.95</b></td></tr> </table>	5 00-15	4 ply	<b>38.95</b>	7.60-15\	8 ply	<b>49.95</b>	10 00-15	8 ply	<b>78.95</b>	12 5L15	8 ply	<b>70.95</b>	<p><b>Firestone AT Field and Road</b></p>  <table border="0"> <tr><td>6-12</td><td>4 ply</td><td><b>54.95</b></td></tr> <tr><td>7-16</td><td>6 ply</td><td><b>88.95</b></td></tr> <tr><td>8-16</td><td>4 ply</td><td><b>98.95</b></td></tr> </table>	6-12	4 ply	<b>54.95</b>	7-16	6 ply	<b>88.95</b>	8-16	4 ply	<b>98.95</b>	<p><b>Firestone Turf &amp; Field</b></p>  <table border="0"> <tr><td>25x8 50-14</td><td>4 ply</td><td><b>76.95</b></td></tr> <tr><td>27x8 50-15</td><td>4 ply</td><td><b>82.95</b></td></tr> <tr><td>13 6-16 . 4 ply</td><td></td><td><b>199.95</b></td></tr> </table>	25x8 50-14	4 ply	<b>76.95</b>	27x8 50-15	4 ply	<b>82.95</b>	13 6-16 . 4 ply		<b>199.95</b>
6 00-16	4 ply	<b>39.95</b>																																																								
7 50-16	6 ply	<b>58.95</b>																																																								
11L15	8 ply	<b>89.95</b>																																																								
10 00-16	8 ply	<b>91.95</b>																																																								
9 5L15	6 ply	<b>79.95</b>																																																								
7 50-16	8 ply	<b>69.95</b>																																																								
11 00-16	8 ply	<b>109.95</b>																																																								
14L16 1	8 ply	<b>223.95</b>																																																								
5 00-15	4 ply	<b>38.95</b>																																																								
7.60-15\	8 ply	<b>49.95</b>																																																								
10 00-15	8 ply	<b>78.95</b>																																																								
12 5L15	8 ply	<b>70.95</b>																																																								
6-12	4 ply	<b>54.95</b>																																																								
7-16	6 ply	<b>88.95</b>																																																								
8-16	4 ply	<b>98.95</b>																																																								
25x8 50-14	4 ply	<b>76.95</b>																																																								
27x8 50-15	4 ply	<b>82.95</b>																																																								
13 6-16 . 4 ply		<b>199.95</b>																																																								

Central Warehouse  
1916 W. Main Street, Mt. Joy, Pa. 17552  
717-653-1260

Branch Warehouse  
Northumberland, Pa.  
717-473-3974 1-800-257-5908

### MUMMAU TIRE SERVICE CENTER

In Pa., Call Toll Free: 1-800-222-1729 NJ, DEL. & MD. - Call 1-800-638-3054

**Firestone**

FARM TIRES  
THE LEADER IN THE FIELD